



## Volkswagen Passat

VIN: 1VWBN7A35CCXXXXXX

2014



Theft



Usage



Odometer



Financial and legal status



Damage



+31

### Data sources

We checked 900+ data sources in 35 countries



Driver & Vehicle  
Licensing  
Agency



Driver & Vehicle  
Standards  
Agency

### Partners


Fuelling this report



# Photos

2017-04

8 photos



# Usage

Was the vehicle used as a taxi, rental or other service vehicle? Note: such vehicles may be in worse condition than usual!



Vehicle was used as a rental!

## Here's what we checked:



### Rental

 Record found

Rental vehicle



### Taxi

✓ No record found

No evidence of being used as a taxi



### Transport

✓ No record found

No evidence of being used as a transport vehicle



### Police

✓ No record found

No evidence of being used by police



### Handicap

✓ No record found

No evidence of being used as a handicap vehicle



### Driving school vehicle

✓ No record found

No evidence of being used as a driving school vehicle

↑ Close

# Theft

Is the vehicle currently marked as stolen?  
Was it stolen in the past? Has it been  
recovered?



Vehicle may be stolen!

## Here's what we checked:



Currently wanted as stolen ?

Record found

Unknown date United Kingdom



Stolen in the past ?

✓ No record found

Current status unknown



Stolen in the past ?

✓ No record found

Vehicle has been recovered

## Police database stolen vehicle check completed in:



United Kingdom

Record found



Czechia



Hungary



Italy



Lithuania







Norway


↑ Close

# Odometer

Are there signs of mileage roll backs or discrepancies?

-  This vehicle may have a fake mileage!
-  Last known mileage: 145,000 mi
-  Average mileage for similar models: 104,200 mi
-  5 mileage records found

 Roll back



↑ Close

# Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection is valid

## Legal



### MOT (technical inspection)

**Passed** 2017-02

United Kingdom

Has successfully passed technical inspection



### Scrap

✓ No record found

No record that vehicle was marked as scrapped



### Exported

**Record found** 2019-09



### Imported

✓ No record found

No import records found

## Outstanding finance



### Lease ?

✓ No record found

No data available on outstanding loan or finance agreement



### Operating-lease ?

✓ No record found

No record of vehicle being on an operating-lease



### Unit-stocking ?

✓ No record found

No record of vehicle being under unit-stocking finance

↑ Close

# Damage

Has this vehicle been damaged in the past?

What was the value of the damages?



This vehicle was damaged 3 times!



Mild damages normally won't impact a vehicle's safety or leave structural issues

## Damage records



Damage

 2018-03

Estimated repair cost

**£9,200** ?

Possible damage cause

**Unknown**

Damage

 2015-07

Estimated repair cost

**£2,400**

Possible damage cause

**Unknown**

Damage

 2014-02

Estimated repair cost

**£1,000**

Possible damage cause

**Unknown**











## Specs & equipment

What specs and equipment are on record for this vehicle?

Check whether the specs and equipment of this vehicle match the facts given by the seller.

### Identification and technical specifications

 Make <b>Volkswagen</b>	 Model <b>Passat</b>	 Body Type <b>Sedan</b>
 Manufacture year <b>2014</b>	 Powertrain displacement <b>2 l</b>	 Powertrain power <b>103 kW (138 hp)</b>
 Gearbox type <b>Automatic</b>	 Plant location <b>Germany</b>	

### Equipment

<b>E6A</b> Special editions <b>No special edition</b>	<b>1PA</b> Lockable wheel bolts <b>Standard wheel bolts</b>
<b>2CU</b> Vehicle class differentiation units/platform components <b>Vehicle class differentiation -360-</b>	<b>7MG</b> Emissions standard <b>Emission standard EU5</b>
<b>1D0</b> Trailer hitch <b>Without trailer hitch</b>	<b>4UE</b> Airbag <b>Air bag for driver and front seat passenger</b>
<b>1E1</b> Activated carbon canister <b>Activated carbon canister</b>	<b>8ZH</b> Antennas <b>Antenna for AM/FM reception, "diversity"</b>
<b>6XU</b> Exterior mirrors <b>automatically dimming, electrically adjustable, separately heated</b>	<b>E40</b> Follow-on warranty <b>Without subsequent warranty</b>
<b>5SL</b> Left exterior mirror <b>aspherical</b>	<b>5BQ</b> Right exterior mirror <b>convex</b>
<b>1X0</b> Drive layout <b>Front wheel drive</b>	<b>9WL</b> "Multimedia", video/DVD/notebook connection <b>Multimedia socket for external audio source</b>
<b>A8B</b> Equipment levels <b>Basic equipment</b>	<b>1KW</b> Brake type in rear <b>Disc brakes, rear</b>
<b>2AA</b> Batteries <b>Battery 340 A (70 Ah)</b>	<b>1ZM</b> Brake type, front <b>Disc brakes, front (Geomet D)</b>
<b>4M3</b> Beverage holders <b>Cup holder</b>	<b>NW9</b> Battery/alternator capacity <b>Standard battery/alternator capacity</b>
<b>86A</b> Component part sets with country-specific design requirements <b>Component parts set without country-specific design requirement</b>	<b>1S1</b> Tool kit and jack <b>Tool kit and jack</b>
<b>1AT</b> Brake systems <b>Electronic stabilization program (ESP)</b>	<b>0XK</b> Owner's manuals <b>Information kit in Lithuanian</b>
<b>5Z0</b> Operating voltage <b>Operating voltage 12V</b>	<b>87B</b> Heated washer nozzles <b>Without heated washer nozzles</b>
<b>7QA</b> CD ROM/DVD/SD card <b>Without CD/DVD for navigation</b>	<b>7M0</b> CD changer/CD player <b>Without CD changer/CD player</b>
<b>2H0</b> Charism <b>Without "drive select"</b>	<b>QJ1</b> Chrome package <b>Chrome work package</b>
<b>C28</b> General operating permit, alterations <b>Operating permit, alterations</b>	<b>350</b> Roof rails/roof load rack <b>Without roof rails/roof load rack</b>
<b>3FA</b> Roof insert/convertible top <b>Without roof insert (standard roof)</b>	<b>1JA</b> Suspension system in rear <b>Rear shock absorption, basic design 1</b>
<b>6G7</b> Suspension system in front <b>Front shock absorption</b>	<b>3X0</b> Ski bag <b>Without load-through provision</b>
<b>XG1</b> Insert for the filling up of unleaded fuel/fuel type <b>Insert for the filling up of unleaded fuel</b>	<b>0EM</b> Installation differentiation for vehicle components <b>Installation differentiation for transmission MQ 200 vehicle components</b>
<b>7AL</b> Theft protection system <b>Anti-theft alarm system, passenger compartment control, backup horn and towing protection</b>	<b>7TM</b> Inserts <b>Decorative inserts</b>
<b>7M0</b> Scaff plates <b>Plastic scaff plates in door apertures</b>	<b>7X0</b> Park distance control <b>Without park distance control</b>
<b>UF3</b> Electric interface for external use <b>Without electric interface</b>	<b>0FG</b> Manufacturing sequence differentiation <b>Mosel manufacturing sequence</b>
<b>2A0</b> Fire extinguishers <b>Without fire extinguisher</b>	<b>VF0</b> Pedal cluster <b>Standard pedal cluster</b>
<b>8K3</b> Headlight control <b>Separate daytime running lights with low beam assistant and "Coming Home" feature</b>	<b>UH2</b> Parking brake <b>Parking brake</b>
<b>7G0</b> Vehicle tracing system <b>Without preparation for VTS (vehicle tracking system)</b>	<b>F0A</b> Vehicle specifications <b>No special purpose vehicle, standard equipment</b>
<b>6G5</b> Alternators <b>Alternator 110 A</b>	<b>0G4</b> Transmission types/gearshift mechanisms <b>Cable gearshift</b>
<b>0VC</b> Weight category rear axle <b>Weight range 3 installation control only, no requirement forecast</b>	<b>101</b> Weight category front axle <b>Suspension range 01 installation control only, no requirement forecast</b>
<b>1U0</b> Base engine <b>4-cylinder gasoline engine 1.4 l unit 03C_K</b>	<b>6M0</b> Tie down straps/net/pocket <b>Without tie down straps/net/pocket</b>
<b>8T0</b> Cruise control system <b>Without cruise control system (CCS)</b>	<b>VC0</b> Garage door opener <b>W/o remote-controlled garage door opener</b>
<b>G0K</b> Transmission specifications <b>6-speed manual transmission</b>	<b>07B</b> Cruise control system and speed limiter <b>W/o cruise control speed limit system</b>
<b>3P1</b> Brackets <b>Bracket for first aid kit and warning triangle</b>	<b>3NU</b> Rear seats <b>Rear seat bench unsplit, backrest split folding with center armrest</b>
<b>KH6</b> Heating and air conditioning system <b>Electronically controlled air conditioning system</b>	<b>8ID</b> Headlamps <b>Halogen twin headlights</b>
<b>7C0</b> Customized installation <b>Without customized installation</b>	<b>6T0</b> Interior light in footwell <b>Without interior light in footwell</b>
<b>USA</b> Instrument clusters <b>Instrument insert, km/h speedometer</b>	<b>4LK</b> Breakaway interior rearview mirror <b>Breakaway interior rear view mirror, automatically dimming</b>
<b>K8B</b> Body style <b>Notchback</b>	<b>QK0</b> Camera/distance sensor <b>Without camera without distance sensor (driver assistance system)</b>
<b>6SE</b> Luggage compartment floor covering <b>Flat needle-punched trunk floor covering</b>	<b>4W0</b> Cassette and CD storage unit <b>Without cassette and CD storage unit</b>
<b>Q40</b> Child seats <b>Without child seat</b>	<b>073</b> Climatic zones <b>Cold zones</b>
<b>Q80</b> Compass/road sign display <b>Without compass/traffic sign display/ traffic signs recognition</b>	<b>4D0</b> Seat ventilation/massage seat <b>Without seat ventilation/massage seat</b>
<b>3Q6</b> Rear head restraints <b>Three rear headrests</b>	<b>5Z1</b> Head restraints <b>Front headrests</b>
<b>1Z0</b> Fuel quantity for initial filling <b>Initial standard fuel filling</b>	<b>1A2</b> Fuel systems <b>Fuel system for SI engine with direct injection (FSI)</b>
<b>5C0</b> Body measures <b>Without special body measures</b>	<b>0K1</b> Radiator grille <b>Radiator grille with chrome-plated strip</b>
<b>6P1</b> Rear license plate carrier <b>License plate bracket rear (ECE)</b>	<b>6W1</b> Front license plate carrier <b>License plate bracket front (large)</b>
<b>5K7</b> Paint preservative/transit coating <b>Transport protection film (minimum protection) with additional transport protection measures</b>	<b>3GA</b> Rear luggage/load compartment floor <b>Without cargo area</b>
<b>FE0</b> Country codes <b>Without country code (no DVD player in vehicle)</b>	<b>1JL</b> Steering system arrangement <b>Right-hand drive vehicle</b>
<b>8S7</b> Reading light <b>Two reading lights front</b>	<b>1N3</b> Steering <b>Speed-related variable steering assist (Servotronic)</b>
<b>3H0</b> Backrest release <b>Without backrest release for front seats</b>	<b>8G0</b> Light control systems <b>Without light assistant</b>
<b>2P1</b> Loading edge protection <b>Plastic trunk sill protection</b>	<b>7P0</b> Lumbar support <b>Without lumbar support in seat backrests</b>
<b>1M8</b> Steering wheels <b>Leather steering wheel</b>	<b>AV1</b> Driving on the left/on the right <b>Driving on the right</b>
<b>8BM</b> Speaker installation <b>8 speakers (passive)</b>	<b>8Q1</b> Headlight range control <b>Headlight-range adjustment</b>
<b>6E3</b> Center armrest <b>Front center armrest</b>	<b>8QB</b> Multi-function display/trip computer <b>Multi-function display with control</b>
<b>315</b> Center console <b>Center console</b>	<b>EM0</b> Driver alert system <b>Without Rest Assist</b>
<b>8Z5</b> Engine cooling system <b>Not hot country</b>	<b>D4K</b> Engine specifications <b>4-cyl. gasoline engine 1.4 l/90 kW TSI Base engine is T0U/TL1/TL4/T98</b>
<b>45G</b> Left vanity mirror <b>Left vanity mirror illuminated extractable sun visor</b>	<b>4TL</b> Right vanity mirror <b>Vanity mirror, right, illuminated extractable sun visor</b>
<b>7Q0</b> Navigation device <b>Without navigation device</b>	<b>8TC</b> Rear fog lamp <b>Rear fog light for driving on the right</b>
<b>8WA</b> Front fog lamp/additional headlamp <b>Without front fog light</b>	<b>1NH</b> Wheel covers <b>Full wheel covers</b>
<b>C20</b> Wheels <b>Steel wheels 6.5J x 16 with optimized weight</b>	<b>8AE</b> Radios <b>Radio "RCD310 MP3"</b>
<b>9JA</b> Smoker's/non-smoker's package <b>Non-smoking package</b>	<b>7N6</b> Direct tire pressure monitoring system <b>Flat tire indicator</b>
<b>1K50</b> Umbrella <b>Without umbrella(s)</b>	<b>H2F</b> Tires <b>Tires 205/55 R16 91H super-optimized rolling resistance</b>
<b>V8A</b> Tire suppliers <b>Tires w/o specification of tire brand</b>	<b>1G2</b> Spare wheel/breakdown kit <b>Steel spare wheel with original equipment tires</b>
<b>3QT</b> Restraint systems, front <b>3-point seat belts with tensioner and height adjustment, front</b>	<b>PA1</b> Leather steering wheel (3-spoke) with decorative aluminum inserts <b>True</b>
<b>1G4</b> Anti-theft alarm system "Plus" <b>True</b>	<b>WFA</b> Family package, Passat station wagon, Sweden <b>True</b>
<b>4X3</b> Side airbag <b>Side air bag front with curtain air bag</b>	<b>6Q2</b> Gearshift knob/handle <b>Leather gearshift knob/handle</b>
<b>25B</b> Special labels/plates <b>Labels/plates in Polish, Estonian, Latvian, Lithuanian, Slovenian</b>	<b>8SG</b> Rear combination lamps <b>Standard taillight assemblies (type 2)</b>
<b>4E7</b> Lock operation for tailgate/trunk lid <b>Tailgate/trunk lid release from inside (electrically)</b>	<b>3TB</b> Front seat, left <b>Standard seat, front left</b>
<b>35B</b> Front seat, right <b>Standard seat, front right</b>	<b>9P1</b> Seat belt check <b>Seat belt reminder, electric contact in buckle</b>
<b>3ZB</b> Outer rear seat belts <b>3-point seat belts, outer rear with ECE label</b>	<b>3CT</b> Center rear seat belts <b>3-point seat belt for center rear seat</b>
<b>N4C</b> Seat trim covers <b>Fabric seat covering</b>	<b>3L3</b> Seat adjustment <b>Manual height adjustment for front seats</b>
<b>2A0</b> Seat heater <b>Without seat heater</b>	<b>7L3</b> Start-stop system/regenerative braking <b>Without start/stop system without regenerative braking</b>
<b>8Y1</b> Horns <b>Two-tone horn</b>	<b>QH0</b> Audio-response system/voice control <b>Without voice control</b>
<b>710</b> Lane change assist/lane keeping system <b>Without lane change assistant</b>	<b>4K0</b> Side and rear windows <b>Side and rear windows in heat-insulating glass</b>
<b>4B1</b> Protective side molding <b>Protective side molding</b>	<b>3Y0</b> Roll-up sun screen for rear and side windows <b>Without roll-up sun screen</b>
<b>7B6</b> Socket <b>12-volt socket(s)</b>	<b>2JB</b> Bumpers <b>Standard bumpers</b>
<b>QN0</b> Drawers under front seats <b>Without drawers under front seats</b>	<b>8X0</b> Headlamp washer system <b>Without headlight washer system</b>
<b>8K3</b> Windshield wiper intermittent control/ light/rain sensor <b>Windshield wiper intermittent control with rain sensor</b>	<b>3M0</b> Special registration measures <b>Without registration measures</b>
<b>2N6</b> Nameplate set <b>Nameplate set in base trim</b>	<b>9A0</b> Special alarm systems <b>Without taxi alarm system</b>
<b>1Q0</b> Mass damper for steering wheels <b>Without mass damper for steering wheel</b>	<b>4K3</b> Door and lid locking system <b>Radio remote controlled central locking operated from inside and safe securing</b>
<b>847</b> Type approval countries/countries with special requirements <b>Type approval the Baltic States</b>	<b>5D1</b> Carrier frequency for radio remote control <b>Carrier frequency 433.92 MHz-434.42 Mhz</b>
<b>3CA</b> Partition <b>Without partition</b>	<b>1TD</b> Transit coating <b>Transit coating (type 1)</b>
<b>3LC</b> Door and side trim panels <b>Door and side trim panel in foam film and woven fabric</b>	<b>QW0</b> TV reception/digital radio reception <b>W/o TV reception/digital radio reception</b>
<b>1VG</b> Installation parts for engine (engine mount system) <b>Installation parts for four-cylinder engine</b>	<b>1SA</b> Front underbody guard <b>Without additional front underbody guard</b>
<b>1EX</b> Identification plates <b>Special identification plate for EC for M1 passenger vehicle</b>	<b>2N0</b> Delivery equipment <b>Without delivery equipment</b>
<b>1T2</b> First aid kit / warning triangle <b>Warning triangle</b>	<b>8D0</b> Preparation for two-way radio installation <b>Without preparation for two-way radio installation</b>
<b>9F0</b> Preparation for sound combination for rotating beacon <b>Without sound combination for rotating beacon light and radio antenna preparation</b>	<b>9W0</b> Telephone / telematics <b>W/o car phone preparation/installation</b>
<b>9TC</b> Additional warning lights <b>Additional reflectors (door area)</b>	<b>QG1</b> Service interval prolongation <b>Service interval prolongation</b>
<b>7ED</b> Heat accumulator system/auxiliary heater <b>W/o heat accumulator/auxiliary heating</b>	<b>4GF</b> Windshield glass type <b>Windshield in heat-insulating glass</b>
<b>8FA</b> Second battery/battery installation <b>Without second battery</b>	<b>2WA</b> Additional tires (snow tires) <b>Without additional tires</b>
<b>Hoor mats</b> <b>Without floor mats</b>	<b>Decorative trims</b> <b>Black moldings</b>
<b>3B4</b> Additional child seat anchors <b>Child seat anchor for child seat system ISOFIX</b>	<b>8M0</b> Auxiliary heater <b>Without auxiliary/parking heater</b>
<b>1UP0</b> Clocks <b>Analog clock</b>	













↑ Close

# Timeline

5 records found

The timeline of records for this vehicle

## Latest records

2014-01  Germany	 <b>Was manufactured</b> The country indicates either the location of manufacturing facility, assembly plant or registration address of the manufacturer. The date may be approximate.
2014-02  United Kingdom	 <b>Was registered</b> The record represents an administrative event. This could be related to a change of ownership, documents, etc
2017-02  United Kingdom	 <b>Was inspected</b> A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.
2018-03  United Kingdom	 <b>Damage detected</b>  We have indications that this vehicle was recognised as damaged in this particular country. Please refer to the 'Damage' section for details.
2020-02  United Kingdom	 <b>Wanted</b>  The vehicle was declared as stolen in this particular country. It is purely the 'origin of theft', and does not cover all the jurisdictions otherwise involved.

↑ Close



+31

### Data sources

We checked 900+ data sources in 35 countries



Driver & Vehicle  
Licensing  
Agency



Driver & Vehicle  
Standards  
Agency

### Partners

Fuelling this report

